

Test Products International (TPI) Europe Ltd

Unit 6

Rutherford Way Industrial Estate

Rutherford Way

Crawley

West Sussex

RH10 9LN

Tel: +44 (0) 1293 530196 sales@tpieurope.com www.tpieurope.com

COMBUSTION EFFICIENCY ANALYSERS (FLUE GAS ANALYSERS)

CONDITION BASED MONITORING (VIBRATION ANALYSERS)

INTRINSICALLY SAFE INSTRUMENTS

OSCILLOSCOPES

DIGITAL CLAMP-ON METERS

DIGITAL MULTIMETERS

DIGITAL MANOMETERS (PRESSURE)

TEMPERATURE INSTRUMENTS

COMBUSTIBLE GAS DETECTORS

GAS DETECTION ACCESSORIES

INDOOR AIR QUALITY (IAQ) MONITORS

REFRIGERANT LEAK DETECTORS

INFRARED NON-CONTACT THERMOMETERS

POCKET DIGITAL THERMOMETERS

DIGITAL VACUUM GAUGE

ELECTRICAL TESTERS

HUMIDITY TESTERS

AIRFLOW TESTERS

TEST LEADS

SERVICE & CALIBRATION

ACCESSORIES

Test Products International Europe Ltd, Registered in England No. 4255058

Registered Office:

4 Heath Square, Boltro Road Haywards Heath, West Sussex. RH16 1BL

VAT registered:

No. 772 6587 86

Test Products International Europe Ltd (TPI Europe)

offers a 'Three Year Limited Warranty' on instruments except intrinsically safe models which have a 'One Year Limited Warranty'.

TPI Europe's obligation is limited to repair or replacement of the product, at TPI Europe's option.

TPI products are warranted to the purchaser against defects in material and workmanship, subject to these products also undergoing annual calibration checks, where applicable.

The warranty period begins from the date of shipment from TPI Europe.

Covered by Warranty:

Repair parts and labour costs, or replacement of the product at TPI Europe's option.

Normal transportation charges back to the purchaser.

Not covered by Warranty:

Damages to the product which are the result of abuse, improper use, or lack of regular maintenance, including annual calibration checks, are not covered.

Calibration, wear from normal use, and consumable items like batteries, fuses, and test leads are not covered. Any other expense, consequential damages, incidental damages, or incidental expenses including damages to property are not covered.

Transportation expenses to TPI Europe are not covered.

